

## **URGENT BULLETIN - FAULTY I-BEAM CLAMPS:**

Safway Services, Inc. has notified Bechtel regarding a discovery of a small percentage of Gravlock beam clamps that do not meet manufacturer's specifications. Rather than conduct a field investigation of the clamps in question, the manufacturer has requested that the clamps be exchanged and taken out of service.

Safway has arranged for other acceptable beam clamps (manufactured by Boulton), to be available for this exchange and is prepared to work with us to facilitate the process. For more information, please contact Rich Smith with Safway at [richs@safwaysupply.com](mailto:richs@safwaysupply.com).

Further details are provided at <http://www.safway.com/index.html>



**Gravlock Beam Clamp**